

4. Mac M4 display connection options

Apple has changed the Thunderbolt on the M4 Macs and it seems that is not 100% Thunderbolt backwards compatible, causing many devices to not work as they did with previous Apple Silicon Macs.

The MP Controller's display does not receive a video signal when using Thunderbolt USB-C on the M4 as it did on previous Apple Silicon Macs.

You should use an HDMI connection for video signal and USB-C (USB-C or USB-A if using a docking station) for the touch data and for providing power to the display.

“ You can optionally (recommended on Model 2A) also use the additional power port using a wall adapter to provide power to the display so that it draws less power from your Mac.

If you need an additional HDMI ports you can use a USB-C docking station like [these](#) offered on Amazon.

Revision #2

Created 24 April 2025 13:19:21 by Admin

Updated 2 August 2025 14:22:00 by Admin